



**FLG INTERNATIONAL LTD**

TECHNICAL SECTION  
FRAME 9001E

---

Compressor Rotor  
Turbine Rotor

## ROTOR DATA

Both Turbine and Compressor Rotors have been operated and maintained according to OEM standards. The Turbine and Compressor Rotors have been fully repaired and in Dec 2019 the rotors were fully inspected and went through a complete Run out check and balancing and are confirmed to be in line with OEM spec/standard.

The Rotors are ready to be installed and operated. Rotors are currently stored in Pressurized Containers with N2 @ 3psi

No.	Description	Serial No.	Hours / Starts
1	Compressor Rotor	G01443621	127,265 / 283
2	Turbine Rotor	G0361449	80,715 / 474

[Info@flg-int.com](mailto:Info@flg-int.com)







TURBINE  
ROTOR



TURBINE  
ROTOR

